nqa global assurance

This is to certify that the Quality Management System of:

# North Star Imaging, Inc.

19875 S. Diamond Lake Road Rogers MN 55374 United States of America

(Central function listed above. See appendix for additional locations)

applicable to:

# The Design, Manufacture, Sales, Installation, Training, and Servicing of Industrial X-Ray Imaging Systems; Provider of Industrial X-Ray Imaging Services

has been assessed and approved by National Quality Assurance, U.S.A., against the provisions of:

## ISO 9001:2015

For and on behalf of NQA, USA



Certificate Number: 14874 EAC Code: 19, 18 Certified Since: June 13, 2013 Valid Until: June 7, 2025 Reissued: July 17, 2023 Cycle Issued: June 8, 2022

Page 1 of 3

This approval is subject to the company maintaining its system to the required standard, which will be monitored by NQA, USA, 289 Great Road, Suite 105, Acton, MA 01720, an accredited organization under the ANSI National Accreditation Board.

Appendix to Certificate Number: 14874

### **Includes Facilities Located at:**

North Star Imaging, Inc. Certificate Number 14874 19875 S. Diamond Lake Road Rogers MN 55374 United States of America

#### North Star Imaging - UK

Certificate Number 14874 Instron House Coronation Road High Wycombe, Buckinghamshire HP12 3SY United Kingdom

#### North Star Imaging, Inc.

Certificate Number 14874 6700 Shadowridge Drive Suite 100 Orlando FL 32812 United States of America

North Star Imaging, Inc. Certificate Number 14874 490 Boston Post Road Sudbury MA 01776 United States of America The Design, Manufacture, Installation, Training and Servicing of Industrial X-Ray Imaging Systems; Provider of Industrial X-Ray Imaging Services; System Sales Office

Service – Provider of Industrial X-Ray Imaging Services; System Sales Office

Service- Provider of Industrial X-Ray Imaging Services; System Sales Office

Service – Provider of Industrial X-Ray Imaging Services

> Certified Since: June 13, 2013 Valid Until: June 7, 2025 Reissued: July 17, 2023 Cycle Issued: June 8, 2022

Page 2 of 3

This approval is subject to the company maintaining its system to the required standard, which will be monitored by NQA, USA, 289 Great Road, Suite 105, Acton, MA 01720, an accredited organization under the ANSI National Accreditation Board.

Appendix to Certificate Number: 14874

## **Includes Facilities Located at:**

North Star Imaging, Inc. Certificate Number 14874 25 Journey Aliso Viejo CA 92656 United States of America Service – Provider of Industrial X-Ray Imaging Services

Certified Since: June 13, 2013 Valid Until: June 7, 2025 Reissued: July 17, 2023 Cycle Issued: June 8, 2022

Page 3 of 3

This approval is subject to the company maintaining its system to the required standard, which will be monitored by NQA, USA, 289 Great Road, Suite 105, Acton, MA 01720, an accredited organization under the ANSI National Accreditation Board.